			40	165.00	Rupees One hundred Sixty five only
17	Stainer				
			5	192.50	Rupees One hundred Ninty two & Fifty Paise Only
			26	192.50	Rupees One hundred Ninty two & Fifty Paise Only
18	Brass filter				
			5	121.00	Rupees One hundred twenty One only
			20	121.00	Rupees One hundred twenty One only
19	Labour charges (over hauling only)				
			5	550.00	Rupees Five hundred fifty only
			22	550.00	Rupees Five hundred fifty only
III	MOTOR REPAIRS				
20	Above 4 HP below 5HP Stator (with one year Guarantee)				
			5	5940.00	Rupees Five thousand nine hundred forty only
			20	5940.00	Rupees Five thousand nine hundred forty only
21	Above 4 HP below 5HP Rotor (with one year Guarantee)				
			5	4400.00	Rupees four thousand Four hundred only
			22	4400.00	Rupees four thousand Four hundred only
22	Upper flange				
			5	330.00	Rupees Three hundred thirty only
			21	330.00	Rupees Three hundred thirty only
23	Lower housing				
			11	539.00	Rupees Five hundred thirty nine only
			22	539.00	Rupees Five hundred thirty nine only
24	Lower flange				
			10	407.00	Rupees Four hundred seven only
			10	407.00	Rupees Four hundred seven only
25	Lock ring				
			8	88.00	Rupees eighty eight only
			40	88.00	Rupees eighty eight only
26	Carbon housing				
			4	407.00	Rupees Four hundred seven only
			20	407.00	Rupees Four hundred seven only
27	Thrust bearing block assembly with segment bearing pad				

Signature of the Contractor

Executive Engineer